Previous TXn Firmware version information

TXn Firmware V1.11 for Win

Fixed Bugs

- Fixed a problem in which the alert message "FAN Failed" would very occasionally appear, even though the fan was working properly, when the power was turned on or switched from Standby to On.

- Fixed a problem in which measuring of the impedance may not have been possible when "Calibration" of "Calibration by Pilot Tone" was executed in the Signal Chain Check function.

TXn Firmware V1.10 for Win

New Feature

- The GAIN function was added to each slot input channel, which enables you to easily make input signal levels consistent between analog and digital (slot) inputs.

Improvement

- The oscillator settings are now excluded from scene functions, so that the settings are not affected by scene recall operations.

Fixed Bugs

- Fixed a problem in which the "Power Amp Mode Changed" alert message appeared when starting up the amplifier while the AMP Mode was set to other than STEREO.

- Fixed a problem in which the start-up process might be initiated on the amplifier when a synchronization operation was performed from Amp Editor by the [Amp Editor->Device] direction.